

**STRUCTURAL SAFETY CERTIFICATE**

- NAME OF WORK :** i) Special Repair/Renovation flooring of toilet and misc. work of Vidyalaya Building, Mudkhed, Dist Nanded.  
ii) Special Repair/Renovation of staff quarters, Mudkhed, Dist Nanded.  
iii) Special Repair/Renovation of Campus road (staff/School), Mudkhed, Dist Nanded.

**DATE OF COMPLETION :**

**NAME OF CONSTRUCTION AGENCY :**

Certified that the construction at Kendriya Vidyalaya, has been carried out with proper earthquake provision as per the structural design approved by IIT/Govt Engineering Collage and the building, which has been constructed, is STRUCTUALLY SAFE.

As these are maintenance works, this is not applicable



**प्राचार्य / PRINCIPAL**

केन्द्रीय विद्यालय/Kendriya Vidyalaya  
सी.आर.पी.एफ. मुदखेड/C.R.P.F. Mudkhed  
जि.नांदेड/Dist.Nanded-431306

कार्यपालक अभियंता  
नासिक केन्द्रीय मंडल  
कें. लो. नि. वि. नासिक



**CHAIRMAN**

विद्यालय प्रबंधक समिति  
Vidyalaya Management Committee  
केन्द्रीय विद्यालय सी.आर.पी.एफ. मुदखेड  
Kendriya Vidyalaya CRPF Mudkhed